






CHEVROLET


Aveo (T250/1) 2005/01 ⇒ 2008/05

	Aveo	2005/01 ⇒	 -123935	GB	R190.00	◀▶
		⇒ 2008/05	 123936 -			◀▶


	Aveo	2005/01 ⇒ 2008/05		FC	R190.07	◀▶
--	-------------	-------------------	--	----	----------------	----


Aveo (T250/2) 2008/03 ⇒ 2011/02

	Aveo	2008/03 ⇒ 2011/02		GB	R190.00	◀▶
--	-------------	-------------------	--	----	----------------	----

	Aveo	2008/03 ⇒ 2011/02		FC	R190.07	◀▶
--	-------------	-------------------	--	----	----------------	----


Captiva (C100) 2006/09 ⇒ 2009/09

	Captiva	2006/09 ⇒ 2009/09		HGB	R190.11	◀▶
--	----------------	-------------------	--	-----	----------------	----

	Captiva	2006/09 ⇒ 2009/09		HGB	R190.12	◀▶
---	----------------	-------------------	--	-----	----------------	----


Captiva (C100) 2009/09 ⇒ 2011/02

	Captiva	2009/09 ⇒ 2011/02		HGB	R190.11	◀▶
--	----------------	-------------------	--	-----	----------------	----

	Captiva	2009/09 ⇒ 2011/02		HGB	R190.12	◀▶
--	----------------	-------------------	--	-----	----------------	----

Captiva (C140) 2011/02 ⇒


	Captiva	2011/02 ⇒				◀▶
--	----------------	-----------	--	--	--	----

	Captiva	2011/02 ⇒		HGB	R190.12	◀▶
--	----------------	-----------	--	-----	----------------	----

Cruze 2009/05 ⇒

	Cruze	2009/05 ⇒	 15"	HGB	R153.66	◀▶
--	--------------	-----------	---	-----	----------------	----


		2009/05 ⇒	 16"	HGB	R153.67	◀▶
--	--	-----------	---	-----	----------------	----

	Cruze	2009/05 ⇒		HGB	R153.68	◀▶
--	--------------	-----------	--	-----	----------------	----


		2009/05 ⇒		HGB	R153.69	◀▶
--	--	-----------	--	-----	----------------	----

Epica (V250) 2006/05 ⇒ 2009/09


	Epica	2006/05 ⇒ 2009/09		HGB	R190.06	◀▶
--	--------------	-------------------	--	-----	----------------	----

	Epica	2006/05 ⇒ 2009/09		HGB	R190.05	◀▶
--	--------------	-------------------	--	-----	----------------	----

Evanda (V200) 2005/01 ⇒ 2007/06

	Evanda	2005/01 ⇒ 2007/06	ABS	HGB	R190.09	◀▶
--	---------------	-------------------	------------	-----	----------------	----

		2005/01 ⇒ 2007/06	ABS	HGB	R190.06	◀▶
--	--	-------------------	------------	-----	----------------	----

	Evanda	2005/01 ⇒ 2007/06	ABS	HGB	R190.10	◀▶
--	---------------	-------------------	------------	-----	----------------	----

		2005/01 ⇒ 2007/06	ABS	HGB	R190.05	◀▶
--	--	-------------------	------------	-----	----------------	----



CHEVROLET

Kalos (T200) 2005/01 ⇨ 2008/05

	Kalos	2005/01 ⇨	-123935	GB	R190.00	⇐
		⇨ 2008/05	123936 -			⇐
	Kalos	2005/01 ⇨ 2008/05		FC	R190.07	⇐

Lacetti (J200) 2005/01 ⇨

	Lacetti	2005/01 ⇨		GB	R184.55	⇐
	Lacetti	2005/01 ⇨	ABS	HGB	R190.10	⇐
		2005/01 ⇨	ABS	HGB	R190.05	⇐

Lanos (T100) 1997/09 ⇨ 2002/12

	Lanos 1.3 i/1.5 i	1997/09 ⇨ 2002/12		GB	R190.00	⇐
	Lanos 1.6 i	1997/09 ⇨ 2002/12		GB	R190.01	⇐
	Lanos 1.3 i/1.5 i/1.6 i	1997/09 ⇨ 2002/12		EC	R153.07	⇐

Matiz (M200) 2005/01 ⇨ 2011/02

	Matiz 0.8/1.0	2005/01 ⇨ 2011/02		EC	R184.53	⇐
	Matiz 0.8/1.0	2005/01 ⇨ 2011/02		EC	R184.52	⇐

Nubira III (J200) 2005/01 ⇨ 2009/09

	Nubira	2005/01 ⇨ 2009/09		GB	R184.55	⇐
	Nubira	2005/01 ⇨ 2009/09	ABS	HGB	R190.10	⇐
		2005/01 ⇨ 2009/09	ABS	HGB	R190.05	⇐

Orlando (J309) 2011/01 ⇨

	Orlando	2011/01 ⇨	15	HGB	R153.66	⇐
		2011/01 ⇨	16	HGB	R153.67	⇐
	Orlando	2011/01 ⇨				⇐

Rezzo (U100) 2005/01 ⇨ 2008/06

	Rezzo 1.6 i/2.0 i	2005/01 ⇨ 2008/06		GB	R184.55	⇐
	Rezzo 1.6 i/2.0 i	2005/01 ⇨ 2008/06	ABS	TGB	R190.03	⇐
		2005/01 ⇨ 2008/06	ABS	TGB	R190.08	⇐

Spark (M200) 2005/05 ⇨ 2009/12

	Spark 0.8 i/1.0 i	2005/05 ⇨ 2009/12		EC	R184.53	⇐
	Spark 0.8 i/1.0 i	2005/05 ⇨ 2009/12		EC	R184.52	⇐

Tacuma (U100) 2005/01 ⇨ 2008/06

	Tacuma 1.6 i/2.0 i	2005/01 ⇨ 2008/06		GB	R184.55	⇐
	Tacuma 1.6 i/2.0 i	2005/01 ⇨ 2008/06	ABS	TGB	R190.08	⇐
		2005/01 ⇨ 2008/06	ABS	TGB	R190.03	⇐