







DAEWOO



Aranos 1995/02 ⇨ 2005/07

	Aranos	1995/02 ⇨ 2005/07	GB	R153.15	◀▶
	Aranos	1995/02 ⇨ 2005/07	EC	R153.07	◀▶



Espero 1993/09 ⇨ 1999/05

	Espero 1.5 i/1.8 i/2.0 i	1993/09 ⇨ 1999/05	GB	R153.15	◀▶
	Espero 1.5 i/1.8 i/2.0 i	1993/09 ⇨ 1999/05 	EC	R153.07	◀▶
		1993/09 ⇨ 1999/05 	HGB	R153.23	◀▶



Evanda (V200) 2002/08 ⇨ 2005/05

	Evanda	2002/08 ⇨ 2005/05 ABS	HGB	R190.09	◀▶
		2002/08 ⇨ 2005/05 ABS	HGB	R190.06	◀▶
	Evanda	2002/08 ⇨ 2005/05 ABS	HGB	R190.10	◀▶
		2002/08 ⇨ 2005/05 ABS	HGB	R190.05	◀▶

Kalos (T200) 2002/09 ⇨ 2005/07

	Kalos	2002/09 ⇨ 2005/07	GB	R190.00	◀▶
	Kalos	2002/09 ⇨ 2005/07	FC	R190.07	◀▶

Lacetti 2003/10 ⇨ 2004/12

	Lacetti	2003/10 ⇨ 2004/12	GB	R184.55	◀▶
	Lacetti	2003/10 ⇨ 2004/12 ABS	HGB	R190.10	◀▶
		2003/10 ⇨ 2004/12 ABS	HGB	R190.05	◀▶



DAEWOO

DAEWOO

Lanos (T100) 1997/09 ⇒ 2005/07

	Lanos 1.3 i/1.5 i	1997/09 ⇒ 2005/07	GB	R190.00	◀▶
	Lanos 1.6 i	1997/09 ⇒ 2005/07	GB	R190.01	◀▶
	Lanos 1.3 i/1.5 i/1.6 i	1997/09 ⇒ 2005/07	EC	R153.07	◀▶

Leganza (V100) 1997/09 ⇒ 2003/01

	Leganza 2.0 i/2.2 i	1997/09 ⇒ 2003/01	GB	R184.55	◀▶
	Leganza 2.0 i/2.2 i	1997/09 ⇒ 2003/01 ABS /	TGB	R190.02	◀▶
	Leganza 2.0 i 16V/2.2 i 16V	1997/09 ⇒ 2003/01 ABS /	TGB	R190.04	◀▶

Matiz (M100) 1998/03 ⇒ 2000/09

	Matiz 0.8 i	1998/03 ⇒ 2000/09	EC	R184.53	◀▶
	Matiz 0.8 i	1998/03 ⇒ 2000/09	EC	R184.52	◀▶

Matiz Facelift (M100) 2000/10 ⇒ 2005/01

	Matiz 0.8 i	2000/10 ⇒ 2005/01	EC	R184.53	◀▶
	Matiz 0.8 i	2000/10 ⇒ 2005/01	EC	R184.52	◀▶

Musso 1999/01 ⇒ 2005/07

	Musso	1999/01 ⇒ 2005/07	EC	R185.02	◀▶
	Musso	1999/01 ⇒ 2005/07			◀▶

Nexia 1995/03 ⇒ 2005/07

	Nexia 1.5	1995/03 ⇒ 2005/07	EC	R153.14	◀▶
	Nexia 1.5 16V	1995/03 ⇒ 2005/07	EC	R153.15	◀▶
	Nexia	1995/03 ⇒ 2005/07	EC	R153.07	◀▶

Nubira (J100) 1997/09 ⇒ 1999/05

	Nubira 1.6 i/2.0 i	1997/09 ⇒ 1999/05	GB	R190.01	◀▶
	Nubira 1.6 i/2.0 i	1997/09 ⇒ 1999/05	EC	R153.07	◀▶

Nubira II (J150) 1999/06 ⇒ 2004/09


	Nubira 1.6 i/2.0 i	1999/06 ⇒ 2004/09	GB	R190.01	◀▶
	Nubira 1.6 i/2.0 i	1999/06 ⇒ 2004/09	EC	R153.07	◀▶

Nubira III (J200) 2003/07 ⇒ 2005/07

	Nubira	2003/07 ⇒ 2005/07	GB	R184.55	◀▶
	Nubira	2003/07 ⇒ 2005/07 ABS	HGB	R190.10	◀▶
		2003/07 ⇒ 2005/07 ABS	HGB	R190.05	◀▶



Rexton 2002/06 ⇒ 2005/07

	Rexton	2002/06 ⇒ 2005/07			◀▶
	Rexton	2002/06 ⇒ 2005/07			◀▶





DAEWOO



Rezzo (U100) 2000/04 ⇒ 2005/07

	Rezzo 1.6 i/1.8 i/2.0 i	2000/04 ⇒ 2005/07	GB	R184.55	◀▶
	Rezzo 1.6 i/1.8 i/2.0 i	2000/04 ⇒ 2005/07 ABS	TGB	R190.08	◀▶
		2000/04 ⇒ 2005/07 ABS	TGB	R190.03	◀▶

Tacuma (U100) 2000/06 ⇒ 2005/07

	Tacuma 1.6 i/1.8 i/2.0 i	2000/06 ⇒ 2005/07	GB	R184.55	◀▶
	Tacuma 1.6 i/1.8 i/2.0 i	2000/06 ⇒ 2005/07 ABS	TGB	R190.08	◀▶
		2000/06 ⇒ 2005/07 ABS	TGB	R190.03	◀▶

Tico 1992/01 ⇒ 2005/07

	Tico	1992/01 ⇒ 1993/10	AB	R177.09	◀▶
		1993/11 ⇒ 2005/07	AB	R184.54	◀▶
	Tico	1992/01 ⇒ 2005/07	AB	R177.08	◀▶