



**OPEL**

**Ascona A** 1970/08 ⇒ 1975/07

	<b>Ascona A</b>	1970/08 ⇒ 1975/07	EC	<b>R153.03</b>	◀▶
	<b>Ascona A</b>	1970/08 ⇒ 1975/07			◀▶

**Ascona B** 1975/08 ⇒ 1981/07

	<b>Ascona B</b>	1975/08 ⇒ 1981/07	EC	<b>R153.07</b>	◀▶
	<b>Ascona B</b>	1975/08 ⇒ 1981/07			◀▶

**Ascona C** 1981/08 ⇒ 1988/08

	<b>Ascona C 1300/1300 S</b>	1981/08 ⇒ 1988/08	GB	<b>R153.14</b>	◀▶
	<b>Ascona C 1600 D</b>	1981/08 ⇒ 1988/08	GB	<b>R153.15</b>	◀▶
	<b>Ascona C 1600</b>	1981/08 ⇒ 1988/08	GB	<b>R153.14</b>	◀▶
		1981/08 ⇒ 1988/08  16SV, E16NZ, C16NZ, C16LZ	GB	<b>R153.14</b>	◀▶
		1981/08 ⇒ 1988/08  16N, 16S, 16SH	GB	<b>R153.15</b>	◀▶
	<b>Ascona C 1800 / 2000</b>	1981/08 ⇒ 1988/08	GB	<b>R153.15</b>	◀▶
	<b>Ascona C</b>	1981/08 ⇒ 1988/08	EC	<b>R153.07</b>	◀▶

**Astra F** 1991/09 ⇒ 2001/02

	<b>Astra</b>	1991/09 ⇒ 2001/02	(34x64x37)	GB	<b>R153.14</b>	◀▶
		1991/09 ⇒ 2001/02	(39x72x37)	GB	<b>R153.15</b>	◀▶
		1991/09 ⇒ 2001/02	(34x66x37)	GB	<b>R153.25</b>	◀▶
		1991/09 ⇒ 2001/02	(39x74x39)	GB	<b>R153.26</b>	◀▶
	<b>Astra</b>	1991/09 ⇒ 2001/02	<b>ABS</b>	HGB	<b>R153.23</b>	◀▶
		1991/09 ⇒ 2001/02	<b>ABS</b>	HGB	<b>R153.22</b>	◀▶

**Astra G** 1998/02 ⇒ 2005/12

	<b>Astra</b>	1998/02 ⇒ 2005/12	<b>ABS</b> /	HGB	<b>R153.31</b>	◀▶
		1998/02 ⇒ 2005/12	<b>ABS</b> /	HGB	<b>R153.30</b>	◀▶
		1998/02 ⇒ 2005/12	<b>ABS</b> /	HGB	<b>R153.32</b>	◀▶
		1998/02 ⇒ 2005/12	<b>ABS</b> /	HGB	<b>R153.33</b>	◀▶
	<b>Astra</b>	2001/03 ⇒ 2005/12	<b>ABS</b> /	HGB	<b>R153.22</b>	◀▶
		2001/03 ⇒ 2005/12	<b>ABS</b> /	HGB	<b>R153.34</b>	◀▶
		1998/02 ⇒ 2005/12	<b>ABS</b> /	HGB	<b>R153.23</b>	◀▶
		1999/10 ⇒ 2005/12	<b>ABS</b> /	HGB	<b>R153.27</b>	◀▶

**Astra Classic** 1998/09 ⇒ 2002/12

	<b>Astra Classic</b>	1998/09 ⇒ 2002/12	(34x66x37)	GB	<b>R153.25</b>	◀▶
	<b>Astra Classic</b>	1998/09 ⇒ 2002/12	<b>ABS</b>	HGB	<b>R153.23</b>	◀▶
		1998/09 ⇒ 2002/12	<b>ABS</b>	HGB	<b>R153.22</b>	◀▶

**Astra H** 2004/03 ⇒

	<b>Astra</b>	2004/03 ⇒		HGB	<b>R153.47</b>	◀▶
	<b>Astra 1.3 CDTI/1.4 i/1.6 i/1.8 i</b>	2004/03 ⇒		HGB	<b>R153.48</b>	◀▶



OPEL

Astra H 2004/03 ⇒

Astra GTC 1.9 CDTi 16V (m Z19DTH)

2004/07 ⇒ HGB **R153.44** <>

Astra 2.0 i Turbo 16V OPC (m Z20LEH)

2004/07 ⇒ HGB **R153.44** <>

Astra 1.7 CDTi Z17DTH,Z17DTL 2004/03 ⇒

HGB **R153.48** <>

Astra 1.7 CDTi A17DTJ,Z17DTJ 2004/03 ⇒

- 62079978 / HGB **R153.53** <>

2004/03 ⇒ - 65076709 / HGB **R153.53** <>

2004/03 ⇒ - 68027072 / HGB **R153.53** <>

62079979 - / HGB **R153.48** <>

65076710 - / HGB **R153.48** <>

68027073 - / HGB **R153.48** <>

Astra 1.9 CDTi/2.0 i

2004/03 ⇒ - 62034695 / HGB **R153.48** <>

2004/03 ⇒ - 65076709 / HGB **R153.48** <>

2004/03 ⇒ - 68027072 / HGB **R153.48** <>

62034696 - / HGB **R153.53** <>

65076709 - / HGB **R153.53** <>

68027072 - / HGB **R153.53** <>



Astra

2004/03 ⇒ HGB **R153.50** <>

2004/03 ⇒ HGB **R153.49** <>

Astra J 2009/09 ⇒



Astra 1.4i/1.4 Turbo/1.6 i/1.3 CDTi 2009/09 ⇒

15" HGB **R153.66** <>

Astra 1.6 i Turbo / 1.7 CDTi / 2.0 CDTi

2009/09 ⇒ 16" HGB **R153.67** <>



Astra 1.4i/1.4 Turbo/1.6 i/1.3 CDTi 2009/09 ⇒

15" HGB **R153.68** <>

Astra 1.6 i Turbo / 1.7 CDTi / 2.0 CDTi

2009/09 ⇒ 16" HGB **R153.69** <>

Calibra 1989/09 ⇒ 1997/07



Calibra 2.0 i C20NE

1989/09 ⇒ - S1999999, S9999999, N9299999, N1299999 GB **R153.15** <>

⇒ 1997/07 T1000001, T9000001, P1000001, P9000001 - GB **R153.26** <>

Calibra 2.0 i 16S C20XE 1989/09 ⇒ 1997/07

GB **R153.26** <>

Calibra 2.0 i X20XEV

1989/09 ⇒ - S1999999, S9999999, N9299999, N1299999 GB **R153.15** <>

⇒ 1997/07 T1000001, T9000001, P1000001, P9000001 - GB **R153.26** <>

Calibra 2.0 i turbo 16S C20LET

1992/03 ⇒ - S1999999, S9999999, N9299999, N1299999 GB **R153.15** <>

⇒ 1997/07 T1000001, T9000001, P1000001, P9000001 - GB **R153.26** <>

Calibra 2.5 i V6

1993/05 ⇒ 1997/07 GB **R153.26** <>



Calibra

1989/09 ⇒ 1997/07 GB **R153.20** <>



**OPEL**

**Campo** 1988/10 ⇒ 1996/06

	<b>Campo</b>	1988/10 ⇒ 1996/06 4x4	EC	<b>R153.42</b>	◀▶
		1988/10 ⇒ 1996/06	EC	<b>R153.28</b>	◀▶
	<b>Campo</b>	1988/10 ⇒ 1996/06	EC	<b>R153.29</b>	◀▶

**Campo** 1996/07 ⇒ 2002/09

	<b>Campo 2.5 DTI/2.5 TD/3.1 TDS</b>	1996/07 ⇒ 2002/09 4x4	EC	<b>R153.42</b>	◀▶
		1996/07 ⇒ 2002/09	EC	<b>R153.28</b>	◀▶
	<b>Campo 2.5 DTI/2.5 TD/3.1 TDS</b>	1996/07 ⇒ 2002/09	EC	<b>R153.29</b>	◀▶

**Commodore C** 1978/08 ⇒ 1982/07

	<b>Commodore 2.5 i/2.5</b>	1978/08 ⇒ 1982/07  - 91362917	EC	<b>R153.11</b>	◀▶
		1978/08 ⇒ 1982/07  91362918 -	EC	<b>R153.16</b>	◀▶
	<b>Commodore 2.5 i/2.5</b>	1978/08 ⇒ 1982/07	AB	<b>R153.09</b>	◀▶

**Corsa A** 1982/10 ⇒ 1993/01

	<b>Corsa</b>	1982/10 ⇒ 1993/01  34x64x37	GB	<b>R153.14</b>	◀▶
		1982/10 ⇒ 1993/01 $\varnothing$ 66 mm	GB	<b>R153.25</b>	◀▶
	<b>Corsa</b>	1982/10 ⇒ 1993/01	EC	<b>R153.07</b>	◀▶

**Corsa B** 1993/03 ⇒ 2000/08

	<b>Corsa</b>	1993/03 ⇒ 2000/08	GB	<b>R153.25</b>	◀▶
	<b>Corsa</b>	1993/03 ⇒ 2000/08	EC	<b>R153.07</b>	◀▶

**Corsa C** 2000/09 ⇒ 2003/08

	<b>Corsa</b>	2000/09 ⇒ 2003/08	GB	<b>R153.39</b>	◀▶
	<b>Corsa</b>	2000/09 ⇒ 2003/08	TGB	<b>R153.38</b>	◀▶
		2000/09 ⇒ 2003/08	FC	<b>R153.37</b>	◀▶

**Corsa C Facelift** 2003/09 ⇒ 2006/07

	<b>Corsa 1.0 / 1.2 / 1.3 CDTi / 1.4 / 1.8</b>	2003/09 ⇒ 2006/07	GB	<b>R153.39</b>	◀▶
	<b>Corsa 1.7 CDTi</b>	2003/09 ⇒ 2006/07	GB	<b>R153.15</b>	◀▶
	<b>Corsa</b>	2003/09 ⇒ 2006/07	FC	<b>R153.37</b>	◀▶
		2003/09 ⇒ 2006/07	TGB	<b>R153.38</b>	◀▶

**Corsa D** 2006/07 ⇒

	<b>Corsa 1.0 i/1.2 i/1.4 i</b>	2006/07 ⇒	GB	<b>R153.57</b>	◀▶
	<b>Corsa 1.3 CDTi/1.7 CDTi/1.6 Turbo</b>	2006/07 ⇒	GB	<b>R153.55</b>	◀▶
	<b>Corsa</b>	2006/07 ⇒	TGB	<b>R153.52</b>	◀▶
		2006/07 ⇒	TGB	<b>R153.51</b>	◀▶



**OPEL**

**Frontera A** 1991/03 ⇒ 1998/09

	<b>Frontera</b>	1991/03 ⇒ 1998/09	EC	<b>R153.42</b>	◀▶
	<b>Frontera</b>	1991/03 ⇒ 1995/04	AB	<b>R141.33</b>	◀▶
		1995/04 ⇒ 1998/09	AB	<b>R141.35</b>	◀▶

**Frontera B** 1998/10 ⇒ 2005/07

	<b>Frontera 2.2 DTi/2.2 i/3.2 i</b>	1998/10 ⇒ 2005/07	EC	<b>R153.42</b>	◀▶
	<b>Frontera 2.2 DTi/2.2 i/3.2 i</b>	1998/10 ⇒ 2005/07	AB	<b>R141.35</b>	◀▶

**Insignia** 2009/01 ⇒

	<b>Insignia</b>	2009/01 ⇒	HGB	<b>R153.58</b>	◀▶
	<b>Insignia</b>	2009/01 ⇒	HGB	<b>R153.59</b>	◀▶
	<b>Insignia 4WD</b>	2009/01 ⇒ 4x4	HGB	<b>R153.63</b>	◀▶

**Kadett B** 1965/09 ⇒ 1973/07

	<b>Kadett B</b>	1965/09 ⇒ 1973/07	EC	<b>R153.03</b>	◀▶
	<b>Kadett B 1100 / 1200</b>	1965/09 ⇒ 1973/07	AB	<b>R153.06</b>	◀▶
	<b>Kadett B 1700 / 1900</b>	1965/09 ⇒ 1973/07	AB	<b>R153.10</b>	◀▶

**Kadett C** 1973/08 ⇒ 1979/07

	<b>Kadett C 1000/1200 S</b>	1973/08 ⇒ 1975/12	EC	<b>R153.03</b>	◀▶
		1973/08 ⇒ 1975/12	EC	<b>R153.03</b>	◀▶
		1976/01 ⇒ 1979/07	EC	<b>R153.07</b>	◀▶
		1976/01 ⇒ 1979/07	EC	<b>R153.07</b>	◀▶
	<b>Kadett C 1600 S/1900/2000 E</b>	1975/08 ⇒ 1979/07	EC	<b>R153.07</b>	◀▶
	<b>Kadett 1000 /1200</b>	1973/08 ⇒ 1979/07	AB	<b>R153.06</b>	◀▶
	<b>Kadett 1600 /1900/2000</b>	1975/08 ⇒ 1979/07	AB	<b>R153.10</b>	◀▶

**Kadett D** 1979/08 ⇒ 1984/08

	<b>Kadett D Caravan 1.0/1.2/1.3/Kadett D 1.0/1.2/1.3</b>	1979/08 ⇒ 1984/08	GB	<b>R153.14</b>	◀▶
	<b>Kadett D Caravan 1.6 D/1.6/Kadett D 1.6 D/1.6/1.8 i</b>	1981/09 ⇒ 1984/08	GB	<b>R153.15</b>	◀▶
	<b>Kadett</b>	1979/08 ⇒ 1984/08	EC	<b>R153.07</b>	◀▶

**Kadett E** 1984/08 ⇒ 1991/01

	<b>Kadett E 1.2 S/1.3/1.4</b>	1984/08 ⇒ 1991	GB	<b>R153.14</b>	◀▶
		1984/08 ⇒ 1991 $\varnothing$ 66 mm	GB	<b>R153.25</b>	◀▶
	<b>Kadett E 1.5 TD</b>	1984/08 ⇒ 1991	GB	<b>R153.15</b>	◀▶
	<b>Kadett E 1.6 m 16SV,C16LZ,C16NZ,E16NZ</b>	1984/08 ⇒ 1991	GB	<b>R153.14</b>	◀▶
		1984/08 ⇒ 1991 $\varnothing$ 66 mm	GB	<b>R153.25</b>	◀▶
	<b>Kadett E 1.6 S  16S-OHC</b>	1984/08 ⇒ 1991	GB	<b>R153.15</b>	◀▶



**OPEL**

**Kadett E** 1984/08 → 1991/01

	<b>Kadett E 1.6 D</b>	1984/08 → 1991	GB	<b>R153.15</b>	◀▶
	<b>Kadett E 1.7D/1.8/2.0 16V/2.0 GSi</b>	1984/08 → 1991	GB	<b>R153.15</b>	◀▶
	<b>Kadett Combo</b>	1984/08 → 1991	EC	<b>R153.16</b>	◀▶
	<b>Kadett</b>	1984/08 → 1991	EC	<b>R153.07</b>	◀▶

**Manta B** 1975/08 → 1988/08

	<b>Manta</b>	1975/08 → 1988/08	EC	<b>R153.07</b>	◀▶
	<b>Manta 1200 N/1200 S/1300 N/1600 N</b>	1975/08 → 1981/07	AB	<b>R153.06</b>	◀▶
	<b>Manta 1300 S/1600 S/1900 N/2.0 S/2000 E</b>	1975/08 → 1988/08	AB	<b>R153.10</b>	◀▶
	<b>Manta 1900 S</b>	1975/08 → 1978/07	AB	<b>R153.10</b>	◀▶
	<b>Manta 1800 S</b>	1982/03 → 1986/07	AB	<b>R153.10</b>	◀▶

**Meriva A** 2003/05 → 2010/07

	<b>Meriva 1.3 CDTi/1.4 i/1.6 i/1.6 i 16V/1.7 DTi/1.8 i</b>	2003/05 → 2010/07	GB	<b>R153.39</b>	◀▶
	<b>Meriva 1.6 Turbo 16V OPC / 1.7 CDTi</b>	2003/08 → 2010/07	GB	<b>R153.15</b>	◀▶
	<b>Meriva 1.3 CDTi</b>	2003/08 → 2010/07 <b>ABS</b>	HGB	<b>R153.22</b>	◀▶
		2003/08 → 2010/07 <b>ABS</b>	HGB	<b>R153.23</b>	◀▶
	<b>Meriva 1.3 CDTi 16V</b>	2003/08 → 2010/07 ☹	HGB	<b>R153.23</b>	◀▶
		2003/08 → 2010/07 ☹	HGB	<b>R153.27</b>	◀▶
	<b>Meriva 1.4 i/1.6 i/16 i 16V/1.7 DTi/1.8 i</b>	2003/05 → 2010/07 <b>ABS</b>	HGB	<b>R153.22</b>	◀▶
		2003/05 → 2010/07 <b>ABS</b>	HGB	<b>R153.23</b>	◀▶
	<b>Meriva 1.6 Turbo 16V OPC</b>	2003/08 → 2010/07	HGB	<b>R153.27</b>	◀▶
	<b>Meriva 1.7 CDTi</b>	2003/08 → 2010/07	HGB	<b>R153.27</b>	◀▶

**Meriva B** 2010/05 →

	<b>Meriva</b>	2010/05 →			◀▶
	<b>Meriva</b>	2010/05 →	HGB	<b>R153.49</b>	◀▶

**Monterey** 1991/09 → 1998/06

	<b>Monterey</b>	1991/09 → 1998/06	EC	<b>R153.42</b>	◀▶
	<b>Monterey</b>	1991/09 → 1998/06			◀▶

**Monterey** 1998/07 → 1999/08

	<b>Monterey</b>	1998/07 → 1999/08	EC	<b>R153.42</b>	◀▶
	<b>Monterey</b>	1998/07 → 1999/08			◀▶

**Monza** 1978/06 → 1986/08

	<b>Monza 2.0 i/2.2 i/2.5 i/3.0 (i)</b>	1981/06 → 1986/08	EC	<b>R153.16</b>	◀▶
--	--	-------------------	----	----------------	----



OPEL

**Monza** 1978/06 ⇒ 1986/08

	<b>Monza 2.8</b>	1978/06 ⇒	- C91362917	EC	<b>R153.11</b>	◀▶
		⇒ 1981/05	C91362918 -	EC	<b>R153.16</b>	◀▶
	<b>Monza</b>	1978/06 ⇒ 1986/08		GB	<b>R153.13</b>	◀▶

**Omega A** 1986/10 ⇒ 1994/02

	<b>Omega</b>	1986/10 ⇒ 1994/02		TGB	<b>R153.19</b>	◀▶
	<b>Omega 1.8 i/1.8/2.0 i/2.3 D</b>	1986/10 ⇒ 1994/02		GB	<b>R153.24</b>	◀▶
	<b>Omega 2.3 TD/2.4 i/2.6 i/3000 i/3.6 i Lotus</b>	1986/10 ⇒ 1994/02		GB	<b>R153.20</b>	◀▶
	<b>Omega</b>	1986/10 ⇒ 1994/02		GB	<b>R153.20</b>	◀▶

**Omega B** 1994/02 ⇒ 2003/07

	<b>Omega</b>	1994/02 ⇒ 2003/07		TGB	<b>R153.19</b>	◀▶
	<b>Omega</b>	1994/02 ⇒ 2003/07		GB	<b>R153.26</b>	◀▶
		1994/02 ⇒ 2003/07		GB	<b>R153.20</b>	◀▶
		1994/02 ⇒ 2003/07		GB	<b>R153.20</b>	◀▶

**Rekord D** 1972/01 ⇒ 1977/08

	<b>Rekord</b>	1972/01 ⇒ 1977/08		EC	<b>R153.07</b>	◀▶
	<b>Rekord</b>	1972/01 ⇒ 1977/08		AB	<b>R153.08</b>	◀▶

**Rekord E** 1977/08 ⇒ 1986/09

	<b>Rekord 1.7</b>	1977/08 ⇒ 1986/09		EC	<b>R153.07</b>	◀▶
		1977/08 ⇒ 1986/09		EC	<b>R153.16</b>	◀▶
	<b>Rekord 1.8</b>	1977/08 ⇒ 1986/09		EC	<b>R153.07</b>	◀▶
	<b>Rekord 1.9 / 2.0 / 2.0 S</b>	1977/08 ⇒ 1986/09		EC	<b>R153.07</b>	◀▶
		1977/08 ⇒ 1986/09		EC	<b>R153.16</b>	◀▶
	<b>Rekord 2.0 E</b>	1977/08 ⇒ 1986/09	- 11028762	EC	<b>R153.16</b>	◀▶
		1977/08 ⇒ 1986/09	11028763 -	EC	<b>R153.07</b>	◀▶
	<b>Rekord 2.2 E</b>	1984/11 ⇒ 1986/09		EC	<b>R153.07</b>	◀▶
	<b>Rekord 2.1 D/2.2 D/2.2 TD/2.3 D</b>	1977/08 ⇒ 1986/09		EC	<b>R153.16</b>	◀▶
	<b>Rekord</b>	1977/08 ⇒ 1986/09		AB	<b>R153.08</b>	◀▶

**Senator A** 1978/06 ⇒ 1987/02

	<b>Senator 2.0 i/2.2 i/2.3 TD/2.5 i</b>	1981/06 ⇒ 1987/02		EC	<b>R153.16</b>	◀▶
	<b>Senator 2.8 / 3.0</b>	1978/06 ⇒	- C91362917	EC	<b>R153.11</b>	◀▶
		⇒ 1987/02	C91362918 -	EC	<b>R153.16</b>	◀▶
	<b>Senator</b>	1978/06 ⇒ 1987/02		GB	<b>R153.13</b>	◀▶

**Senator B** 1987/02 ⇒ 1993/06

	<b>Senator 2.5 i/2.6 i/3.0 i</b>	1987/02 ⇒ 1993/06		TGB	<b>R153.19</b>	◀▶
	<b>Senator 2.5 i/2.6 i/3.0 i</b>	1987/02 ⇒ 1993/06		GB	<b>R153.20</b>	◀▶



**OPEL**

**Signum A** 2003/06 ⇒ 2005/09

	<b>Signum</b>	2003/06 ⇒	/  - 41999999	HGB	<b>R153.40</b>	◀▶
		2003/06 ⇒	/  - 41999999	HGB	<b>R153.43</b>	◀▶
		2003/06 ⇒	51000001 -	HGB	<b>R153.43</b>	◀▶
	<b>Signum</b>	2003/06 ⇒ 2005/09		HGB	<b>R153.41</b>	◀▶

**Signum B** 2005/10 ⇒ 2008/11

	<b>Signum</b>	2005/10 ⇒ 2008/11		HGB	<b>R153.43</b>	◀▶
	<b>Signum</b>	2005/10 ⇒ 2008/11		HGB	<b>R153.41</b>	◀▶

**Sintra** 1996/03 ⇒ 1999/12

	<b>Sintra</b>	1996/03 ⇒ 1999/12		HGB	<b>R153.64</b>	◀▶
	<b>Sintra</b>	1996/03 ⇒ 1999/12		HGB	<b>R153.65</b>	◀▶

**Speedster** 2000/08 ⇒ 2005/09

	<b>Speedster 2.0 i/2.2 i</b>	2000/08 ⇒ 2005/09	<b>ABS</b> /	HGB	<b>R153.33</b>	◀▶
	<b>Speedster 2.0 i/2.2 i</b>	2000/08 ⇒ 2005/09	<b>ABS</b> /	HGB	<b>R153.33</b>	◀▶

**Tigra** 1994/10 ⇒ 2001/01



	<b>Tigra 1.4 i/1.6 i</b>	1994/10 ⇒ 2001/01		GB	<b>R153.25</b>	◀▶
	<b>Tigra 1.4 i/1.6 i</b>	1994/10 ⇒ 2001/01		EC	<b>R153.07</b>	◀▶

**Tigra Twintop** 2004/07 ⇒ 2008/07

	<b>Tigra Twintop 1.3 CDTi/1.4 i/1.8 i</b>	2004/07 ⇒ 2008/07		GB	<b>R153.39</b>	◀▶
	<b>Tigra Twintop 1.3 CDTi/1.4 i</b>	2004/07 ⇒ 2008/07		TGB	<b>R153.38</b>	◀▶
	<b>Tigra Twintop 1.8 i</b>	2004/07 ⇒ 2008/07		FC	<b>R153.37</b>	◀▶

**Vectra A** 1988/09 ⇒ 1995/09

	<b>Vectra 1.4</b>	1988/09 ⇒ 1992/07		GB	<b>R153.14</b>	◀▶
	<b>Vectra 1.6S</b> <b>16LZ2</b>	1988/09 ⇒ 1993/12	- P1999999, P5999999, P9999999	GB	<b>R153.15</b>	◀▶
		1994/01 ⇒ 1995/09	R1000001, R5000001, R7500001 -	GB	<b>R153.25</b>	◀▶
	<b>Vectra 1.6S</b> <b>16SV</b>	1988/09 ⇒ 1992/07		GB	<b>R153.14</b>	◀▶
		1988/09 ⇒ 1992/07		GB	<b>R153.15</b>	◀▶
	<b>Vectra 1.6 i</b> <b>C16NZ</b>	1993/09 ⇒ 1993/12	/  - P1999999, P5999999, P9999999	GB	<b>R153.14</b>	◀▶
		1993/12 ⇒ 1995/11	/  R1000001, R5000001, R7500001 -	GB	<b>R153.25</b>	◀▶
	<b>Vectra 1.6 i Auto</b> <b>C16NZ</b>	1988/09 ⇒ 1995/11		GB	<b>R153.25</b>	◀▶
	<b>Vectra 1.6 i</b> <b>C16NZ2</b>	1988/09 ⇒ 1993/12	- P1999999, P5999999, P9999999	GB	<b>R153.15</b>	◀▶
		1993/12 ⇒ 1995/11	R1000001, R5000001, R7500001 -	GB	<b>R153.25</b>	◀▶
	<b>Vectra 1.6 i</b> <b>E16NZ</b>	1988/09 ⇒ 1993/12	- P1999999, P5999999, P9999999	GB	<b>R153.14</b>	◀▶
		1993/12 ⇒ 1993/07	R1000001, R5000001, R7500001 -	GB	<b>R153.25</b>	◀▶
	<b>Vectra 1.6 i</b> <b>X16SZ</b>	1988/09 ⇒ 1993/12	- P1999999, P5999999, P9999999	GB	<b>R153.14</b>	◀▶
		1993/12 ⇒ 1993/07	R1000001, R5000001, R7500001 -	GB	<b>R153.25</b>	◀▶
	<b>Vectra 1.7 D/1.7 TD/1.8 i/2.0 i</b>	1988/09 ⇒ 1995/09		GB	<b>R153.15</b>	◀▶



OPEL

**Vectra A** 1988/09 ⇒ 1995/09

	<b>Vectra 2000 i/ 2000i 16V</b>	1990/03 ⇒ 1995/09	GB	<b>R153.15</b>	◀▶
	<b>Vectra 2000 4x4 Turbo 16V</b>	1992/08 ⇒ 1993/12  - N1999999	GB	<b>R153.15</b>	◀▶
		1994/01 ⇒ 1995/09  P1000001 -	GB	<b>R153.26</b>	◀▶
	<b>Vectra 2.5 i</b>	1993/05 ⇒ 1995/09	GB	<b>R153.26</b>	◀▶
	<b>Vectra 1.4/1.6 i/1.6 S/1.7 D/1.7 TD/1.8 i/2.0 i</b>				
		1988/09 ⇒ 1992/07	EC	<b>R153.07</b>	◀▶
		1992/08 ⇒ 1995/09 <b>ABS</b>	HGB	<b>R153.23</b>	◀▶
		1992/08 ⇒ 1995/09 <b>ABS</b>	HGB	<b>R153.22</b>	◀▶
	<b>Vectra 1.8/2.0 i/2000 i</b>	1988/09 ⇒ 1995/09 4x4	GB	<b>R153.20</b>	◀▶
	<b>Vectra 2.5 i V6</b>	1993/05 ⇒ 1995/09	HGB	<b>R153.27</b>	◀▶

**Vectra B** 1995/10 ⇒ 1999/01

	<b>Vectra</b>	1995/10 ⇒ 1999/01	GB	<b>R153.26</b>	◀▶
	<b>Vectra 1.6 i/1.7 TD/1.8 i/2.0 Di/2.0 Tdi/2.0 i</b>				
		1995/10 ⇒ 1999/01	HGB	<b>R153.23</b>	◀▶
	<b>Vectra 2.0 i/2.5 i/2.5 i500</b>	1995/10 ⇒ 1999/01	HGB	<b>R153.27</b>	◀▶

**Vectra B** 1999/02 ⇒ 2003/06

	<b>Vectra 1.6 i/1.8 i/2.0 DTi/2.2 DTi/2.2 i/2.6 i</b>				
		1999/02 ⇒ 2003/06	GB	<b>R153.26</b>	◀▶
	<b>Vectra 1.6 i/1.8 i/2.0 DTi/2.2 DTi/2.2 i/2.6 i</b>				
		1999/02 ⇒ 2003/06	HGB	<b>R153.23</b>	◀▶
		1999/02 ⇒ 2003/06	HGB	<b>R153.27</b>	◀▶

**Vectra C** 2002/04 ⇒ 2005/09







	<b>Vectra</b>	2002/04 ⇒	IDS /  - 41999999, 48999999	HGB	<b>R153.40</b>	◀▶
		2002/04 ⇒	IDS /  - 41999999, 48999999	HGB	<b>R153.43</b>	◀▶
		⇒ 2005/09	51000001, 58000001 -	HGB	<b>R153.43</b>	◀▶
	<b>Vectra</b>	2002/04 ⇒ 2005/09		HGB	<b>R153.41</b>	◀▶

**Vectra C Facelift** 2005/10 ⇒ 2009/02







	<b>Vectra 1.6 i/1.8 i/1.9 CDTi/2.0 i/2.2 DIG/2.8 i</b>				
		2005/10 ⇒ 2009/02	HGB	<b>R153.43</b>	◀▶
	<b>Vectra 1.6 i/1.8 i/1.9 CDTi/2.0 i/2.2 DIG/2.8 i</b>				
		2005/10 ⇒ 2009/02	HGB	<b>R153.41</b>	◀▶








**OPEL**
**Zafira A (F75) 1998/10 ⇨ 2003/06**

	<b>Zafira</b>	1999/01 ⇨ 2003/06	ABS / 	HGB	<b>R153.32</b>	◀▶
		1999/01 ⇨ 2003/06	ABS / 	HGB	<b>R153.33</b>	◀▶
		1999/01 ⇨ 2003/06	ABS / 	HGB	<b>R153.31</b>	◀▶
		1999/01 ⇨ 2003/06	ABS / 	HGB	<b>R153.30</b>	◀▶
	<b>Zafira</b>	1999/01 ⇨ 2003/06	ABS	HGB	<b>R153.27</b>	◀▶
		1999/01 ⇨ 2003/06	ABS	HGB	<b>R153.34</b>	◀▶

**Zafira A FL (F75) 2003/07 ⇨ 2005/06**

	<b>Zafira</b>	2003/07 ⇨ 2005/06	ABS / 	HGB	<b>R153.32</b>	◀▶
		2003/07 ⇨ 2005/06	ABS / 	HGB	<b>R153.33</b>	◀▶
		2003/07 ⇨ 2005/06	ABS / 	HGB	<b>R153.31</b>	◀▶
		2003/07 ⇨ 2005/06	ABS / 	HGB	<b>R153.30</b>	◀▶
	<b>Zafira</b>	2003/07 ⇨ 2005/06	ABS	HGB	<b>R153.27</b>	◀▶
		2003/07 ⇨ 2005/06	ABS	HGB	<b>R153.34</b>	◀▶

**Zafira B 2005/07 ⇨ 2008/07**

	<b>Zafira 1.6 i/1.7 CDTi/1.8 i/1.9 CDTi/2.2 i/2.0 i Turbo 16</b>	2005/07 ⇨ 2008/07	 - 62034695, 6G019309	HGB	<b>R153.48</b>	◀▶	
		2005/07 ⇨ 2008/07	 62034696, 6G019310 -	HGB	<b>R153.53</b>	◀▶	
		<b>Zafira 1.9 CDTi 16V</b>	2005/07 ⇨ 2008/07	 Z19DTH	HGB	<b>R153.44</b>	◀▶
		<b>Zafira 2.0 i Turbo 16V OPC</b>	2005/07 ⇨ 2008/07		HGB	<b>R153.44</b>	◀▶
	<b>Zafira 1.6 i/1.8 i/1.7 CDTi/1.9 CDTi/2.0 i Turbo/2.2 i</b>	2005/07 ⇨ 2008/07		HGB	<b>R153.49</b>	◀▶	
		<b>Zafira 1.6 GNV</b>	2005/07 ⇨ 2008/07			◀▶	

**Zafira B FL 2008/07 ⇨**

	<b>Zafira 1.6 i</b>	2008/07 ⇨	 Z16XEP	HGB	<b>R153.48</b>	◀▶		
		2008/07 ⇨	 Z16YNG	HGB	<b>R153.53</b>	◀▶		
		2008/07 ⇨	 Z16XNT	HGB	<b>R153.53</b>	◀▶		
		2008/07 ⇨	 Z18XER	HGB	<b>R153.53</b>	◀▶		
		2008/07 ⇨		HGB	<b>R153.53</b>	◀▶		
		2008/07 ⇨	 Z19DT, Z19DTL	HGB	<b>R153.53</b>	◀▶		
		2008/07 ⇨	 Z19DTH	HGB	<b>R153.44</b>	◀▶		
		2008/07 ⇨	 Z20LER	HGB	<b>R153.53</b>	◀▶		
		2008/07 ⇨	 Z20LEH	HGB	<b>R153.44</b>	◀▶		
		2008/07 ⇨		HGB	<b>R153.53</b>	◀▶		
			<b>Zafira 1.6 i</b>	2008/07 ⇨	 Z16XEP	HGB	<b>R153.49</b>	◀▶
				2008/07 ⇨	 Z16YNG			◀▶
				2008/07 ⇨	 Z16XNT			◀▶



**OPEL**

**Zafira B FL 2008/07** ⇨

Zafira 1.7 CDTi/1.8 i/1.9 CDTi/2.2 i/2.0 i Turbo 16

2008/07 ⇨

HGB **R153.49** ⇐⇨

**Zafira C 2011/10** ⇨

**Zafira** 2011/10 ⇨ HGB **R153.67** ⇐⇨

**Zafira** 2011/10 ⇨ HGB **R153.69** ⇐⇨

**Arena 1998/01** ⇨ 2001/08

**Arena 1.9 D** 1998/01 ⇨ - B002817 GB **R155.09** ⇐⇨

⇨ 2001/08 B002818 - GB **R155.14** ⇐⇨

1998/01 ⇨ - B014311 GB **R155.09** ⇐⇨

⇨ 2001/08 B014312 - GB **R155.14** ⇐⇨

**Arena 2.5 D** 1998/01 ⇨ - B002825 GB **R155.09** ⇐⇨

⇨ 2001/08 B002826 - GB **R155.14** ⇐⇨

1998/01 ⇨ - B014308 GB **R155.09** ⇐⇨

⇨ 2001/08 B014309 - GB **R155.14** ⇐⇨

**Arena** 1998/01 ⇨ 2001/08 **ABS** EC **R140.24** ⇐⇨

1998/01 ⇨ 2001/08 **ABS** EC **R140.81** ⇐⇨

**Combo 1985/07** ⇨ 1993/03

**Combo** 1985/07 ⇨ 1993/03 34x64x37 GB **R153.14** ⇐⇨

1985/07 ⇨ 1993/03 66 mm GB **R153.25** ⇐⇨

**Combo** 1985/07 ⇨ 1993/03 EC **R153.07** ⇐⇨

**Combo 1993/03** ⇨ 2001/09

**Combo 1.2 i/1.2/1.4 i/1.7 D** 1993/03 ⇨ 2001/09 GB **R153.25** ⇐⇨

**Combo 1.2 i/1.2/1.4 i/1.7 D** 1993/03 ⇨ 2001/09 EC **R153.16** ⇐⇨

**Combo 2001/10** ⇨ 2004/06

**Combo 1.3 CDTi/1.4 i** 2001/10 ⇨ 2004/06 GB **R153.39** ⇐⇨

**Combo 1.6 i/1.7 DI/1.7 DTi** 2001/10 ⇨ 2004/06 GB **R153.39** ⇐⇨

**Combo 1.7 CDTi** 2001/10 ⇨ 2004/06 Z17DTH GB **R153.15** ⇐⇨

**Combo** 2001/10 ⇨ 2004/06 **ABS** HGB **R153.22** ⇐⇨

**Combo 1.3 CDTi/1.4 i/1.6 i/1.7 Di/1.7 DTi**

2001/10 ⇨ 2004/06 **ABS** HGB **R153.23** ⇐⇨

**Combo 1.7 CDTi** 2001/10 ⇨ 2004/06 **ABS** HGB **R153.27** ⇐⇨

**Combo FL 2004/06** ⇨

**Combo 1.3 CDTi 16V / 1.4 i Twinport 16V / 1.6 i GNV**

2004/06 ⇨ GB **R153.39** ⇐⇨

**Combo 1.7 CDTi 16V** 2004/06 ⇨ 39x72x37 GB **R153.15** ⇐⇨



**OPEL**

**Combo FL 2004/06** ⇨

	<b>Combo 1.3 CDTI 16V / 1.4 i Twinport 16V / 1.6 i GNV / 1.7 CDTI 16V</b>	2004/06 ⇨	<b>ABS</b> /	HGB	<b>R153.22</b>	⇐ ⇨
	<b>Combo 1.3 CDTI 16V / 1.4 i Twinport 16V / 1.6 i GNV</b>	2004/06 ⇨	<b>ABS</b> /	HGB	<b>R153.23</b>	⇐ ⇨
	<b>Combo 1.7 CDTI 16V</b>	2004/06 ⇨	<b>ABS</b> /	HGB	<b>R153.27</b>	⇐ ⇨

**Combo 2011/10** ⇨


	<b>Combo 1.3 CDTI 90 16V / 1.4 i 95 16V / 1.4 CNG Turbo 120 16V / 1.6 CDTI 16V / 2.0 CDTI 135 16V</b>	2011/10 ⇨	<b>ABS</b>	GB	<b>R158.64</b>	⇐ ⇨
		2011/10 ⇨	<b>ABS</b> /	GB	<b>R158.63</b>	⇐ ⇨
		2011/10 ⇨	<b>ABS</b>	GB	<b>R158.54</b>	⇐ ⇨
		2011/10 ⇨	<b>ABS</b> /	GB	<b>R158.65</b>	⇐ ⇨
	<b>Combo 1.3 CDTI 90 16V / 1.4 i 95 16V / 1.4 CNG Turbo 120 16V / 1.6 CDTI 16V / 2.0 CDTI 135 16V</b>	2011/10 ⇨	<b>ABS</b>	TGB	<b>R141.24</b>	⇐ ⇨
		2011/10 ⇨	<b>ABS</b> /	TGB	<b>R141.26</b>	⇐ ⇨
		2011/10 ⇨	<b>ABS</b>	TGB	<b>R141.23</b>	⇐ ⇨
		2011/10 ⇨	<b>ABS</b> /	TGB	<b>R141.25</b>	⇐ ⇨

**Combo Tour 2002/04** ⇨ 2004/06

	<b>Combo Tour 1.3 CDTI/1.4 i/1.6 GNV</b>	2002/04 ⇨ 2004/06		GB	<b>R153.39</b>	⇐ ⇨
	<b>Combo Tour 1.6 i/1.7 DI/1.7 DTi</b>	2002/04 ⇨ 2004/06		GB	<b>R153.39</b>	⇐ ⇨
	<b>Combo Tour 1.7 CDTI</b>	2002/04 ⇨ 2004/06	39x72x37	GB	<b>R153.15</b>	⇐ ⇨
	<b>Combo Tour</b>	2002/04 ⇨ 2004/06	<b>ABS</b>	HGB	<b>R153.22</b>	⇐ ⇨
	<b>Combo Tour 1.3 CDTI/1.4 i/1.6 i/1.7 Di/1.7 DTi</b>	2002/04 ⇨ 2004/06	<b>ABS</b>	HGB	<b>R153.23</b>	⇐ ⇨
	<b>Combo Tour 1.7 CDTI</b>	2002/04 ⇨ 2004/06	<b>ABS</b>	HGB	<b>R153.27</b>	⇐ ⇨






**Combo Tour FL 2004/06** ⇨

	<b>Combo 1.3 CDTI 16V / 1.4 i Twinport 16V / 1.6 i GNV</b>	2004/06 ⇨		GB	<b>R153.39</b>	⇐ ⇨
	<b>Combo 1.7 CDTI 16V</b>	2004/06 ⇨	39x72x37	GB	<b>R153.15</b>	⇐ ⇨
	<b>Combo 1.3 CDTI 16V / 1.4 i Twinport 16V / 1.6 i GNV / 1.7 CDTI 16V</b>	2004/06 ⇨	<b>ABS</b> /	HGB	<b>R153.22</b>	⇐ ⇨
	<b>Combo 1.3 CDTI 16V / 1.4 i Twinport 16V / 1.6 i GNV</b>	2004/06 ⇨	<b>ABS</b> /	HGB	<b>R153.23</b>	⇐ ⇨
	<b>Combo 1.7 CDTI 16V</b>	2004/06 ⇨	<b>ABS</b> /	HGB	<b>R153.27</b>	⇐ ⇨





## OPEL



### Movano A 1998/10 ⇨ 2003/09

	<b>Movano</b>	1998/10 ⇨ 2003/09  16"	FC	<b>R140.06</b>	◀▶
		1998/10 ⇨ 2000/02  15"	FC	<b>R155.64</b>	◀▶
		2000/03 ⇨ 2003/09  15"	FC	<b>R140.06</b>	◀▶
	<b>Movano</b>	1998/10 ⇨ 2002/07  15"	FC	<b>R155.65</b>	◀▶
		1998/10 ⇨ 2003/09  16"	FC	<b>R140.01</b>	◀▶




### Movano A Facelift 2003/10 ⇨ 2006/10

	<b>Movano</b>	2003/10 ⇨ 2006/10	FC	<b>R140.06</b>	◀▶
	<b>Movano</b>	2003/10 ⇨ 2006/10  15"	FC	<b>R155.65</b>	◀▶
		2003/10 ⇨ 2006/10  16"	FC	<b>R140.01</b>	◀▶




### Movano A Facelift 2 2006/10 ⇨

	<b>Movano</b>	2006/10 ⇨	FC	<b>R140.06</b>	◀▶
	<b>Movano</b>	2006/10 ⇨  15"	FC	<b>R155.65</b>	◀▶
		2006/10 ⇨  16"	FC	<b>R140.01</b>	◀▶

### Movano B 2010/05 ⇨

	<b>Movano</b>	2010/05 ⇨			◀▶
	<b>Movano</b>	2010/05 ⇨ 	FC	<b>R141.28</b>	◀▶
		2010/05 ⇨ 			◀▶
		2010/05 ⇨ 			◀▶

### Vivaro 2001/05 ⇨ 2006/07

	<b>Vivaro</b>	2001/05 ⇨  - 3V613233 / <b>ABS</b>	GB	<b>R155.69</b>	◀▶
		2001/05 ⇨  - 3V613233 / <b>ABS</b>	GB	<b>R155.71</b>	◀▶
		2001/05 ⇨ 2006/07  3V613234 -	GB	<b>R155.74</b>	◀▶
	<b>Vivaro</b>	2001/05 ⇨ 2006/07	FC	<b>R155.70</b>	◀▶
		2001/05 ⇨ 2006/07	KF	<b>KF155.70U</b>	◀▶

### Vivaro FL 2006/07 ⇨

	<b>Vivaro</b>	2006/07 ⇨	GB	<b>R155.74</b>	◀▶
	<b>Vivaro</b>	2006/07 ⇨	FC	<b>R155.70</b>	◀▶
		2006/07 ⇨	KF	<b>KF155.70U</b>	◀▶